

Case Scenario

Illicit Connection

Maria Begiebing
Environmental Inspector II
Watershed Enforcement
May 29, 2018



Environmental Services



Delivering world class utility services and programs to improve our health, environment, and economy.

A pipe discharging sewage is discovered by Santa Clara Valley Water District and is located on the bank of Coyote Creek




Delivering world class utility services and programs to improve our health, environment, and economy.

The adjacent area is commercial property with multiple structures with businesses



Delivering world class utility services and programs to improve our health, environment, and economy.

Below is an Aerial View of Location



Dropped Pin

near 693 Quinn Ave, San Jose, CA 95112

[Start \(1 min\)](#)

[Directions](#)



Delivering world class utility services and programs to improve our health, environment, and economy.

Illicit Connection

Creek conditions



Sewage and toilet paper accumulated on bank



Delivering world class utility services and programs to improve our health, environment, and economy.



Questions

1. What steps do you take to identify the source of the discharge?
2. How do you proceed to cease discharge?
3. What action is taken for permanent solution to cease discharge?
4. How do you handle cleanup of creek?
5. What other departments or agencies should be involved?

Cease Discharge (Temporary)



Delivering world class utility services and programs to improve our health, environment, and economy.

Long Term Solution



Delivering world class utility services and programs to improve our health, environment, and economy.

Long Term Solution



Delivering world class utility services and programs to improve our health, environment, and economy.